


Operation of Electronic Throttle Idle Learning on Jeep Wrangler


Jeep Wrangler, VIN=1J4GA59119L*****, throttle pedal position sensor 1 and 2 fault appears. Signal limitation cannot be adjusted. After performing the electronic throttle learning, problem is solved.

Operation Procedure:


- 1). Switch on ignition.
- 2). Select Chrysler version above V29.80.
- 3). Select Chrysler 16PIN.
- 4). Select "Manually Select" (or select automatically scan)
- 5). Select engine system.
- 6). Select "Learn ETC (Electronic Throttle Control)", see picture 1.



7). Operate as prompted. "Press and hold the throttle pedal to the floor. Throttle is widely open". This procedure takes a few seconds. It will prompt "Press and hold accelerator pedal to the floor....."



- 8). Operate as prompted. "Release accelerator pedal and press OK", then it prompts "Do not touch accelerator pedal".



9).It prompts "Learn ETC (Electronic Throttle Control)" succeeded. After confirmation, quit and switch off ignition.

