BMW Maintenance_Reset_Steps 760Li_2011

Tested model: 2011 BMW 760Li

Trouble phenomenon: the instrument alarm prompts the vehicle to be maintained

Solve the problem: reset the maintenance prompt after maintenance is completed

Software version：BMW V50.12

Steps：

Starting conditions: turn on the ignition switch, clear the fault code of the whole vehicle, and the battery voltage is above 12V.

1. Select BMW software to enter, and select special functions to enter;

2. Select the corresponding car series and chassis to enter;

Show Menu

BMW V50.54 > Special Function > 7 Series   11.71V

7'_E23	7'_E32
7'_E38	7'_E65/E66/E67/E68
7'_F01/F02/F03/F04	7'_G11/G12

BMW 7 Series

3. Select the network maintenance (CBS) reset;

Show Menu

BMW V50.54 > Special Function > 7 Series > 7'_F01/F02/F03/F04   11.71V

|	
CBS Reset	CBS Correct
Delete Transport Mode	Set Transport Mode
Steering Angle Learning	Brake Pad Change
Check Control Message	Tyre Air Pressure Warning Lamp Reset (Puncture With Run-Flat Tyre)
Throttle Learning	

BMW 7 Series

4.　　Select software reset to enter;

5. Select engine oil, the system will automatically scan the vehicle maintenance information;

6.   Click "Yes" directly after reading out the maintenance information, and the system can automatically reset;

7.   Prompt that End Of Test Module, click OK to reset successfully.