GM Chevrolet Blazer 2020 Hands-Free Liftgate Sensor Control Module Calibration

Supported equipment: Launch's full range of comprehensive diagnostic equipment

Current equipment: PAD V

Function description: It is necessary to perform this calibration function after replacing the hands-free liftgate sensor.

**Tested model:** 2020 Chevrolet Blazer, VIN: 3GNKBJR45LS6*****

1. It is necessary to stop the vehicle before performing this function. On a PAD V, choose [Local Diagnose].

2. Choose [GM] to test.

3. Choose [Automatically Search] to identify car models automatically.

4. Click [LCM (Liftgate Control Module)] to access the system.

5. Click [Special Functions] and then choose [Remove/Reset Module].

6. Choose [Hands-Free Liftgate Sensor Control Module Calibration].

7. Turn on the ignition switch.

8. The program is in progress, with a countdown of 15 seconds.

9. Function calibration is successful.

Statement:

The content of this document is copyrighted by Shenzhen Launch Tech Co., Ltd., and no individual or organization may quote or reprint it without consent.