

Trumpchi AIONS Replace airbag ECU


Function description: Trumpchi AIONS, replace airbag ECU, need to perform “replace ECU” function.

Supported products: Launch PRO series, PAD series integrated diagnostic device.

Tested model: 2021 year model Trumpchi AIONS with VIN LNAA3AA18M5*****.
(See below figure);



Airbag MIL illuminated. (See below figure);



Operation Guideline:

1. Save DTC report, SRS (Supplemental Restraint System) has 16 fault code.
(See below figure);




Figure 1

2. Enter SRS(Supplemental Restraint System), select “replace ECU”. (See below figure);




Figure 2

3. Check all conditions are met, click “OK”. (See below figure);




Figure 3

4. Check all information is correct, click “OK”. (See below figure);




Figure 4

5. Replacement is successful, click “OK”. (See below figure);




Figure 5

6. SRS(Supplemental Restraint System) has no fault code. (See below figure);




Figure 6

7. Airbag MIL off. (See below figure);



Figure 7

Declaration:

The copyright of this document belongs to Launch Technology Co., Ltd. Any company or individual shall not quote or reprint without permission.