

FIAT Toro MCA Service Information Reset (Service Lamp Reset) Method


Supported equipment: Launch's full range of comprehensive diagnostic equipment


Current equipment: PAD V

Function description: After repair is completed for FIAT, service information reset is required.



Tested model: 2022/Fiat/Toro MCA, VIN: 9882261PHNKE*****

1. On a PAD V, choose [Local Diagnose] and then [FIAT] to test;







- 2. Choose [Automatically Search] to identify car models automatically. After the car model is successfully identified, choose OK;




3. Choose [Yes] to unlock the SGW.




4. Choose [North America] for the region;




5. Input the login user name and password, and click OK;




6. Unlocking is successful. Click OK;





7. Click [Smart Detection] to scan the entire vehicle systems;




8. Click [IPC (Instrument Panel Cluster)] to access the system;




9. Click [Special Function] and click OK;




10. Choose [Misc Function];




11. Choose [Reset Service Information];




12. Click OK;




13. Click OK;



14. Choose [Continue];



15. Click OK. Program execution is completed;



Statement:

The content of this document is copyrighted by Shenzhen Launch Tech Co., Ltd., and no individual or organization may quote or reprint it without consent.