BMW brake warning lamp reset

On some vehicle, brake warning lamp will illuminate after brake pads wear or/and replacement. The best, easiest way to reset it is to use a scanner!

The following is the method to reset brake warning lamp on some BMW new 7 series models (E65) with Launch X-431.

Connect X431 to the car and power on, after download software and initialization finished, please select ChassisCoding and programmingMaintenance E65 SeriesCBS Reset 1, see

Fig.1, Fig.2.

	MAINT	ENANCE	
E87 Serie	8		
E90 Serie	3		
E60/E61 3	eries		
E65 Serie	3		
PAGE UP		PAGE DOWN	
HOME	BACK	PFINI	HELP
Start)	<u>(</u>	3	₩¥ 10:3

MAINTENANCE						
CBS reset	T					
CBS reset 2						
PAGE UP		PAGE DOWN				
HOME	BACK	PPINI	HELP			
Start)	g c	学 ※	₩ 1D:34			

Fig.1

Fig.2

After you click CBS reset 1 as Fig.2, available functions menu display as Fig.3. Select "Front brake" or "Rear brake" according to you have replaced. If the availability present is more than 80%, warning information will be pop up as Fig.4. You can choice to reset or not. If availability is less than 80%, reset will be done automatically without any warning.

MAINTENANCE				
Engine oil	L			
Microfilte	er			
Front brak	te			
Rear brake	2			
Vehicle cr	neck			
PAGE UP		PAGE DOWN		
HOME	BACK	PRINI	HELP	
Start)	ا ل	学 茶	23 10:36	




Fig.3

Fig.4

Note: Please troubleshooting DSC and erase all DTCs stored before performing this function.