

GM Chevrolet Suburban 2021 Transmission

Adaptive Pressure Reset


Supported equipment: Launch's full range of comprehensive diagnostic equipment

Current equipment: PAD 5



Function description: This function needs to be executed when the transmission pressure sensor is replaced or when the vehicle experiences problems such as gear shifting jerking, delay, or impact while driving.

Tested model: 2021 GM Chevrolet Suburban, VIN: 1GNSKDKD9MR*****

1. It is necessary to stop the vehicle before performing this function. On a PAD 5, choose [Local Diagnose].



2. Choose [GM] to test.



GM Diagnose V50.05

INTRODUCTION

This diagnostic software can test the ECUs of GM Models, including:

Engine Control Module, Transmission Control Module, Antilock Braking System, Supplemental Inflatable Restraint, Body Control Module, Instrument Panel Cluster, Heating and Air Conditioning, Tire Pressure Monitor, Electronic Suspension Control, Radio, Driver Door Module, Driver Position Module, Passenger Door Module, Remote Control Door Lock Receiver, Vehicle Comm. Interface Module, Immobilizer, Amplifier and so on.

Basic Functions:



- Reading ECU information
- Reading DTCs
- Clearing DTCs
- Reading vehicle running data
- Vehicle component operation test

Special Functions:



- Engine Control Module:
 - Oil Life Reset
 - Accelerator Pedal Position (APP) Learn





3. Choose [Automatically Search] to identify car models automatically.




4. Operate according to the prompt “Turn Ignition ON (Turn The Key To On Position. For Push-Start Vehicle, Please Long Press The Start Button For 5-10s To Turn Ignition On)”.




5. Click [TCM] to access the system.




6. Click [Special Functions].




7. Click [Transmission Adaptive Pressure Reset].



8. Before the function reset, the status is “None”. Click [Reset].



9. The status changes to “Reset”. The reset is successful.



Statement:

The content of this document is copyrighted by LAUNCH TECH CO., LTD., and no individual or organization may quote or reprint it without consent.