

FIAT Strada Service Information Reset (Service Lamp Reset) Method


Supported equipment: Launch's full range of comprehensive diagnostic equipment



Current equipment: PAD V

Function description: After repair is completed for FIAT, service information reset is required.



Tested models: 2021/Fiat/Strada, VIN: 9BD281A31MYV*****

1. On a PAD V, choose [Local Diagnose] and then [FIAT] to test.







- 2. Choose [Automatically Search] to identify car models automatically. After the car model is successfully identified, choose OK.




3. Choose [Yes] to unlock the SGW.




4. Choose [North America] for the region.




5. Input the login user name and password, and click OK.




6. Unlocking is successful. Click OK.



7. Click [Smart Detection] to scan the entire vehicle systems.



8. Click [IPC (Instrument Panel Cluster)] to access the system.




10. Choose [Misc Function].




11. Choose [Reset Service Information].




12. Click OK.



13. Click OK.



14. Click OK. Program execution is completed.



Statement:

The content of this document is copyrighted by Shenzhen Launch Tech Co., Ltd., and no individual or organization may quote or reprint it without consent.